

1. Measure walls to outside of Window Frames
2. Measure Windows & Doors from outside to outside of their frames
3. Measure a column location off of 2 walls and indicate the size of the column.
4. Measure the ceiling ht. or if there is Crown Molding 8' 0" measure from the floor to the bottom of molding
5. Measure the Windows from the floor up to the bottom of the window sill.

